

## DESCRIPTION

**RIP TIDE** is a heavy duty industrial cleaner and degreaser. It quickly cuts through and lifts the toughest oils, greases, carbon deposits and all types of grime. Oilfield, industrial, marine, and municipal uses are virtually unlimited. **RIP TIDE** may be used through all types of mechanical cleaning equipment including: steam cleaners, pressure washers and automatic scrubbing machines. It may also be used in manual cleaning operations including: spray on/flush off, bucket washing, mopping, scrubbing and bilge cleaning. The special lifting action of this product will allow for easy rinsing and equipment cleaning. Formulated for use with oil separators.

## SPECIAL DILUTIONS

**For Steam Cleaners and Pressure Washers:** To the concentrate solution tank, add 4 to 14 ounces of **RIP TIDE** to each gallon of water. Adjust the solution tank valve to obtain amount of cleaner required for different soil conditions.

**For Automatic Scrubbers:** Increase concentration of use dilution only enough to remove soil present. A 25 to 1 dilution with water is the recommended starting point.

**For Soak Tank or Ultrasonics:** Use 12 ounces per gallon of water.

## General Dilution Table

USES	RIP TIDE	WATER
Light Cleaning	1 part	40 to 100
Medium Cleaning	1 part	20 to 40
Heavy Cleaning	1 part	10 to 20
Extra Heavy Cleaning	1 part	5 to 10



Engineered Chemistries  
**SUPERIOR SOLUTIONS**

# RIP TIDE™

## HEAVY DUTY CLEANER DEGREASER

**CLEANS AND DEGREASES**  
**DISSOLVES OIL AND GREASE**  
**CONTAINS CORROSION INHIBITORS**  
**BIODEGRADABLE**

**DANGER**  
**KEEP OUT OF REACH OF CHILDREN.**  
**FOR INDUSTRIAL AND INSTITUTIONAL USE ONLY.**  
SEE SIDE PANEL FOR ADDITIONAL CAUTIONS.

NET CONTENTS: U.S. GALLON

4/14



## DANGER: Corrosive Liquid

Harmful in contact with skin and if inhaled. Causes severe skin burns and eye damages. May cause an allergic skin reaction.

Do not breathe dusts or mists. Wash hands thoroughly after handling. Wear protective gloves/protective clothing/eye protection/face protection. Contaminated work clothing shouldn't be allowed out of the workplace. Use only outdoors or in a well-ventilated area. If swallowed: Rinse mouth. Do NOT induce vomiting. Immediately call a poison control center/doctor. If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a poison center or doctor. If on skin (or hair): Remove/Take off clothing before reuse. Immediately call a poison center/doctor. If inhaled: Remove person to fresh air and keep comfortable for breathing. Immediately call a poison center/doctor. Store locked up. Dispose of contents and container in accordance with all local, regional, national and international regulations.

READ SAFETY DATA SHEET BEFORE USE.

Proper Shipping Name: NA 1760, Compounds, Cleaning Liquid, (Potassium Hydroxide), 8, PGI



WEICHEM, INC.  
5734 Susitna Dr.  
Harahan, LA 70123  
504.733.1152  
1.800.426.0512  
FAX 504.733.2218  
www.wechem.com



7 38435 20612 3